

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY www.nr.utah.gov

July 1, 2003

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Hydrologist

RE:

Site Inspection, Gemstone Mining, Inc., Red Beryl Mine, M/001/045, Beaver County,

Utah

Date of Inspection:

June 18, 2003

Time of Inspection:

10:00 a.m. to 11:30 a.m.

Conditions:

Sunny and hot

Participants:

Tom Munson, DOGM

## **Purpose of Inspection:**

To examine the site to determine the success of fall of 2002 seeding

### **Observations:**

The following were found growing on site: grasses - foxtail, crested wheatgrass, smooth brome, and indian ricegrass - shrubs: fourwing, and forage kochia; and - weeds: tumbleweed. and halogenten. There were very few penstemon, about three total. The road still exists on site and a small cabin exists in the area where the pad remains. A shed that was near the cabin is now demolished; the lumber and tinder, from that shed, was piled on site. A fuel storage pit area with a plastic liner is still on site adjacent to the pile of lumber from the shed. The unreclaimed disturbance is bonded for reclamation by Red Emerald, Inc.

I left the site about 11:30.

### **Conclusions and Recommendations:**

No reseeding should occur until the weather patterns change significantly, so that the disposition of seed for revegetation will have the potential to be successful. I will contact the Red Emerald folks about the remaining debris, the propane tank and toilets which remain on the site.

jb

cc: Dominique Merz, Gemstone Mining Co.

Earle Foster, Red Emerald, Inc.

Ed Ginouves, BLM



## ATTACHMENT

# Photographs M/001/045, Red Beryl Mine, Gemstone Mining, Inc. Inspection Dated: 6/18/2003; Report Dated: 7/1/2003




Photo 1 - Regrading with no vegetation success



Photo 3 - Upper Pit with nothing growing




Photo 2 - Regrading with no vegetation success



Photo 4-upper pit area

Page 2 M/001/045 Red Beryl Mine 7/01/2003



Photo 5 - propane storage tank



Photo 6 - remains of fuel storage area



Photo 7- tipped over bathroom



Photo 8 - Cabin

Page 3 M/001/045 Red Beryl Mine 7/01/2003



Photo 9 - forage kocia?



Photo 10 - old shed garbage



Photo 11 - vegetation on the lower pad